

From: North America Product Management

To: North America Customers

Date: October 13, 2021

Subject: AG Reciprocating Compressor Model Number Printed Labels – Serial and Carton

## PRODUCT BULLETIN

## **DESCRIPTION OF ISSUE**

Tecumseh has identified an issue with the printing of the AG reciprocating R22 service replacement compressor model number only on both the serial label and the carton label on the outside of the single pack. The item number is correct in all cases and there is <u>no issue</u> with the compressor itself. All other markings (voltage, refrigerant, etc) are correct. The differences in the model nomenclature printing of the labels may prompt questions from the field, which are being addressed with this bulletin cross reference below.

AG Reciprocating Service Compressor Nomenclature – Serial and Carton Label

ITEM NUMBER  (No issues, labeled correctly)	MODEL NUMBER  (Correct nomenclature - as shown on the wholesale price list – product labels  October 2021 and forward)	MODEL Nomenclature on AG compressor product labels produced up to  August 2021	MODEL Nomenclature on AG compressor product labels produced in  September 2021
AG122EF-104-J7	AGB5553ECZ	AG5553E	AG5553E-CZ
AG122RF-104-J7	AGB5553EKZ	TAG5553E	TAG5553E-KZ
AG122UF-104-J7	AGB5553ETZ	TAG5553E	TAG5553E-TZ
AG133EF-105-J7	AGB5561ECZ	AG5561E	AG5561E-CZ
AG133RF-104-J7	AGB5561EKZ	TAG5561E	TAG5561E-KZ



ITEM NUMBER  (No issues,  labeled correctly)	MODEL NUMBER  (Correct nomenclature - as shown on the wholesale price list – product labels  October 2021 and forward)	MODEL Nomenclature on AG compressor product labels produced up to <u>August 2021</u>	MODEL Nomenclature on AG compressor product labels produced in  September 2021
AG133UF-104-J7	AGB5561ETZ	TAG5561E	TAG5561E-TZ
AG144RF-105-J7	AGB5568EKZ	TAG5568E	TAG5568E-KZ
AG144SF-105-J7	AGB4568ZKZ	TAG4568Z	TAG4568Z-KZ
AG144UF-105-J7	AGB5568ETZ	TAG5568E	TAG5568E-TZ
AG188UF-105-J7	AGB5573ETZ	TAG5573E	TAG5573E-TZ

## **BACKGROUND**

Beginning in 2021, as a part of Tecumseh's Portfolio Optimization, AG compressors are now manufactured at our Tecumseh plant in Europe. Previously, the compressors were final assembled, including labeling at our plant in Mississippi. A data error, which has been corrected, resulted in a different model number being printed on the affected labels (serial and carton). **Incorrect** label example shown to the right.



## **IMPACT OF CHANGES / QUESTIONS**

No issues with the compressor itself, it is correct, only the "model" nomenclature shows different than indicated on the price list. All other markings (voltage, refrigerant, etc) are correct as shown. Any questions, contact your Tecumseh Regional Sales Manager or Technical Support (technical support@tecumseh.com).